

State Route 2017, Section 570 Station Hill Road over Norfolk Southern Railroad

EXISTING CONDITION

1. SEVERE STRUCTURAL DETERIORATION
2. BRIDGE CLOSED IN 2019
3. 72 VEHICLES PER DAY
4. ALTERNATIVE ROUTES CURRENTLY IN USE

ALTERNATIVES EVALUATED

1. BRIDGE REHABILITATION
2. BRIDGE REPLACEMENT
3. BRIDGE REMOVAL



PRELIMINARY PLANS DISPLAY